EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2712	(shear\$4 near3 (measur\$5 indicat\$4 meter \$4 test\$4 detect \$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat \$5 transducer gauge cell monitor\$4 comput\$5 inspect \$5 meter calculat \$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2008/03/29 11:10
L2	702	1 and (driv\$5 motive motion moving).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2008/03/29 11:11
L3	227	2 and ((velocity speed acceleration position) near3 (measur\$5 indicat\$4 meter \$4 test\$4 detect \$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat \$5 transducer gauge cell monitor\$4 comput\$5 inspect \$5 meter calculat \$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2008/03/29 11:12
L4	3	3 and (wall near3 shear near3 stress). clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2008/03/29 11:14
L5	9	3 and (wall near3 shear near3 stress)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2008/03/29 11:18

L6	9987	(73/760-841). CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2008/03/29 11:26
L7	4	6 and (wall near3 shear near3 stress). clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2008/03/29 11:28

3/29/08 11:29:27 AM

C:\ Documents and Settings\ MNoori\ My Documents\ EAST\ Workspaces\ max.wsp